

ALERTS

LEARNING FROM OTHERS

Hydraulic Ram Top Link

A hydraulic top link has snapped with the attachment dropping. In this situation a post rammer was attached with potential for a worker traveling behind the tractor on a 2-wheel motorbike being hit. The weld had some visible rust.



TO AVOID THIS HAPPENING TO YOU:

- Please check all welds on hydraulic components for any visible rust, cracking, or paint discolouration.
- If an issue is identified, please report to your manager for follow-up investigation.